

FIG. 1




FIG. 3A




FIG. 3B





FIG. 3C




FIG. 3D

FIG. 4A




FIG. 4B





FIG. 4C




FIG. 4D

Diagram illustrating a sliding surface 16 moving to the right over a stationary surface 15. The sliding surface 16 is shown as a series of steps or a sawtooth pattern, while the stationary surface 15 is a flat line. An arrow indicates the direction of movement.



FIG. 7A





FIG. 7B



CASSETTE FILLED BY SAMPLE




FIG. 7C




FIG. 7D

SAMPLE
OUT

T00220" 9205T860

FIG. 8A

7/8




FIG. 8B





FIG. 8C




FIG. 8D

FIG. 9B




FIG. 9A





FIG. 9C